



Joseph M. Lafata
(248) 641-1223
jmlafata@hdp.com

January 11, 2007

Director of the USPTO
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
JAN 17 2007
of Correction

Re: Patent No: 7,111,699
Issued: September 26, 2006
Serial No.: 10/731,744; Filed: December 9, 2003
Inventor: Michael S. MacConney, et al.
For: Engine Governor System
Our File No.: 3191E-000043/US

Sir:

We have noted in proofreading Patent No. 7,111,699 the following errors:

Column 4, line 1 (application page 7, line 18), "positioned" should be ~~position~~.

Column 4, line 41 (application page 9, line 2), "rpm's" should be ~~rpms~~.

Column 4, line 51 (application page 9, line 10), after "formed" insert ~~in~~.

Column 6, line 5 (application page 12, line 8), "exceed" should be ~~exceeded~~.

Very truly yours,

/Joseph M. Lafata/

Joseph M. Lafata
Reg. No. 37,166

JML/kk